25 METERS ZEROING TARGET
M16A2

Oberland Arms
Where Innovation is @ Home !



ZERO TARGET DATA

1- ROTATE REAR SIGHT ELEVATION KNOB TO THE 8/3 SETTING, THEN UP (RIGHT) ONE CLICK PAST THE 300 MARK, FOR ZEROING AT 25 METERS.

2- AIM AT TARGET CENTER, ADJUST SIGHTS TO MOVE SHOT GROUP CENTER AS CLOSE AS POSSIBLE TO THE WHITE DOT IN CENTER OF THE TARGET.

3- AFTER COMPLETION OF THE 25 METER ZERO, ROTATE THE REAR SIGHT ELEVATION KNOB BACK ONE CLICK TO THE 300/800 METER MARK, THE WEAPON WILL BE ZEROED FOR 300 METERS.